


Third floor:  
Bucket ½ filled with rain water after  
a storm.



3<sup>rd</sup> floor Hallway:  
Ceiling tile water damage and mold.



Fire escape:  
Roof shingles falling off roof.



Roof above Conference Room:  
Many different repairs above  
Chambers area